
ELEVATOR INSTALLATIONS quick view









TRACTEL®'S UNIQUE TEST PLATES

TA test plates are test specimens endowed with a breaking section calibrated to break under a determined traction force. It is the fastest and simplest way to determine that a lifting point can safely pull a determined capacity.

Tractel[®] offers several types of anchor testers calibrated to break with a tolerance range of $\pm 10\%$.



www.tractel.com

PRODUCT LINE CARD

LIFTING AND HANDLING

